

ERS Remediates Gas Skid Units at New England Power Plant

Customer Pain Point

- ✓ *A New-England power plant experienced repeated wet/dry cycles that deteriorated coating on piping and skids*
- ✓ *Extreme peeling, blistering, and rusting of piping and skid area were difficult to address due to hard to reach areas*

The ERS Solution

- ✓ *ERS prepared and coated piping with a Macropoxy and Hi Solids Epoxy system*
- ✓ *ERS prepared and coated skid with ERS 80RS Rust Stopper for a long-term rust and degradation remediation*

ERS Differentiator

- ✓ *Eliminated need for disassembly of equipment*
- ✓ *Fast cure times reducing down-time of skid area*
- ✓ *Extended useful life of equipment*



www.RESINTEAM.com
610-874-8436
418 W Front Street
Chester, PA 19013

A DIVISION OF

